

EAST Search History

Ref #	Hits	Search Query	DBs	Default Operator	Plurals	Time Stamp
L3	96556	(bobbin spool (coil adj support) (coil adj former)) with (array series set contact\$3 connect\$3)	US_PGPUB; USPAT; USOOR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2008/02/15 12:35
L4	60970	3 and (wire coil wind\$3)	US_PGPUB; USPAT; USOOR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2008/02/15 12:36
L5	31408	3 with (wire coil wind\$3)	US_PGPUB; USPAT; USOOR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2008/02/15 12:37
L6	3092	5 with magnetic	US_PGPUB; USPAT; USOOR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2008/02/15 12:38
L7	1	6 with (electrodynamic adj machine)	US_PGPUB; USPAT; USOOR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2008/02/15 12:39
L8	1	6 same (electrodynamic adj machine)	US_PGPUB; USPAT; USOOR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2008/02/15 12:39
L9	4	6 and (electrodynamic adj machine)	US_PGPUB; USPAT; USOOR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2008/02/15 12:40

L10	1276	6 and (motor machine)	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2008/02/15 12:40
L11	559	6 same (motor machine)	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2008/02/15 12:41
L12	394	6 with (motor machine)	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2008/02/15 12:41
L13	165	11 not 12	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2008/02/15 12:48
L14	293	6 same (transformer)	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2008/02/15 13:06
L15	24898	((bobbin spool (coil adj support) (coil adj former)) AND (array series set contact\$3 connect\$3)). clm.	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2008/02/15 13:13
L16	23877	((bobbin spool (coil adj support) (coil adj former)) AND (array series set contact\$3 connect\$3)). clm.	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2008/02/15 13:13
L17	4534	((bobbin spool (coil adj support) (coil adj former)) AND (array series set contact\$3 connect\$3)). clm.	US-PGPUB	OR	OFF	2008/02/15 13:13
L18	1278	((bobbin spool (coil adj support) (coil adj former)) AND (array series set contact\$3 connect\$3)AND (transformer motor machine)).clm.	US-PGPUB	OR	OFF	2008/02/15 13:15

L19	250	((bobbin spool (coil adj support) (coil adj former)) AND (array series set contact\$3 connect\$3) AND magnetic AND (transformer motor machine)).clm.	US-PGPUB	OR	OFF	2008/02/15 13:15
L20	929	336/208.ccls.	USPAT	OR	OFF	2008/02/15 13:20
L21	26	L20 and @pd>"20060828"	US-PGPUB; USPAT; USOOR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2008/02/15 13:20
L22	1560	4 and "310"/\$.ccls.	US-PGPUB; USPAT; USOOR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2008/02/15 13:42
L23	1210	22 and magnetic	US-PGPUB; USPAT; USOOR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2008/02/15 13:43
L24	1263	22 and (transformer machine motor)	US-PGPUB; USPAT; USOOR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2008/02/15 13:45
L25	222	22 and 10	US-PGPUB; USPAT; USOOR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2008/02/15 13:47
L26	0	21 and 10	US-PGPUB; USPAT; USOOR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2008/02/15 13:50
L27	9	22 and 14	US-PGPUB; USPAT; USOOR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2008/02/15 13:50

2/15/2008 1:51:15 PM

C:\Documents and Settings\jbaisa\My Documents\EAST\Workspaces\10540222.wsp